

SCHEDULE No. 33

The zone boundary limits identified by 33 can be more particularly identified in the "Reassessment of Slope Stability, Lower Mercer Street, Lyndale Estates Subdivision, Kitchener" prepared by LVM, dated September 14, 2011.